

Menu


HISTORY FILE MAP for year 2001

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



281.08:30-08:31 & 281.08:33-08:53: 21m realtime 1024bps data lost at DSS24 due to transmitter trip-off. The uplink low elevation interlock was not disabled. Additional 2-way to 1-way to 2-way transitions. DR G100394 refers.

281.09:11-09:27, 281.09:43-09:45 & 281.10:06-10:13: 25m realtime 1024bps data lost at DSS24. Track was broken due to an incorrect cable wrap. Additional 2-way to 1-way to 2-way transitions. DR G100395 refers.